

PR001  
04-Mar-11

# Preliminary Report of Accident

U.S. Department of Labor  
Mine Safety and Health Administration



1. Accident Type: Fatal Injury		2. Accident Classification Falling, Rolling or Sliding Rock /Materl		3. Date/Time of Accident 03/02/2011 04:51 PM		4. Date/Time of Death 03/02/2011 05:50 PM		5. Fatal Case No 2		
6. Mine Information :										
a) Mining Company Name PCS Phosphate Company Inc			b) Mine Name Lee Creek Mine			c) Parent of Mining Company Potash Corp Of Saskatchewan				
7. Mine Location :		a) City Aurora		b) County Beaufort		c) State NC		8. Mine ID Number: 31-00212		9. Union: NO
10. Primary Mineral Mined: PHOSPHATE ROCK MINING		11. Number of Mine Employees:		a) Total 385		b) Underground 232		c) Open Pit/Quarry 123		d) Mill/Prep Plant 30
12. Contractor Name: Trader Construction						13. Union NO		14. Contractor ID Number: IQ6		
15. Contractor Address:		a) City New Bern		b) County Craven		c) State NC		d) Zip Code 28562		
16. Number of Contractor Employees:		a) Total 152		b) Underground 79		c) Open Pit/Quarry 20		d) Mill/Prep Plant 53		e) Other
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:				
a) Mine Employees: 152		b) Contractor Employees: 79		a) Mine Employees: 0		b) Contractor Employees: 0				
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground		<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility		Feet Inches		
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1								
23. Victim Information :		a) Name David E. Clark		b) Age 51						
c) Regular Job Title: Superintendent		d) Activity at Time of Accident: Placing pipe in fuser								
		<input checked="" type="checkbox"/> Contractor Employee								
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days		
a) Total:		24 0 0		b) at the mine: 20 0 0		c) at activity (23d) 10 0 0		d) with Contractor 24 0 0		
25. Autopsy Performed: If Yes, Location YES Beaufort Co., NC						26. Mine Telephone No.:				
27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations): The victim was attempting to join two ends of 24-inch pipe. An excavator bucket was being used to position the pipe in the saddle of a pipe fuser. The pipe slipped out of the saddle and struck him.										
28. Equipment Manufacturer: McElory						29. Model: A3640101				
30. District: M3000 Southeastern				32. Field Office: Sanford NC			33. Event Number: 6528034			
34. Accident Investigator: Billy Ratliff				35. MSHA Person Notified: Doniece L. Schlick			Date 03/02/2011		Time 05:14 P	
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Mike Hancher				Date 03/04/2011				
38. Reason For Amendment:										